



MATERIALS:

copper spray paint
half yard of pink satin fabric
socket with cord
40 watt light bulb
metallic cardstock
scissors

sharp razor tool hot glue gun small screwdriver nose pliers



Spray paint your hat and once dry, use the hot glue gun to adhere the ribbon around the base of the hat.



Measure and cut the metallic cardstock to fit in the inside of the hat and glue down.



Disassemble the light socket from cord and disconnect the wires.



Screw in the bulb, hang your hat.



Make a hole in the center of the hat. Thread the wires through the hole and reattach socket inside the hat.



Plug it in and you have light!



